


EXAMPLE OF DAMAGE TO A SOLAR PANEL



On this panel the defect is more pronounced. We can see, in this photo, darkening of the area in question. Replacement of the panel is necessary to reduce risk of fire and damage to other panels.